Michael O. Leavitt

DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING



INSPECTION REPORT

1594 West North Temple, Suite 1210

PO Box 145801

Salt Lake City, Utah 84114-5801

801-538-5340 801-359-3940 (Fax)

Lowell P. Braxton Division Director

Governor

801-538-7223 (TDD)

Partial: XXX Complete: Exploration: Inspection Date & Time: 11/22/99 / 11:30a.m.-3:00p.m.

Date of Last Inspection: 10/28/99

Mine Name: Willow Creek Mine County: Carbon Permit Number: ACT/007/038						
Permittee and/or Operator's Name: Plateau Mining Corporation						
Business Address: 847 Northwest Highway 191, Helper, Utah 84526						
Type of Mining Activity: Underground XXX Surface Prep. Plant Other						
Company Official(s): Johnny Pappas						
State Officials(s): Peter Hess Federal Official(s): None						
Weather Conditions: Sunny, Windy, Cold, 30's						
Existing Acreage: Permitted-14,670 Disturbed-161.55 Regraded- Seeded- Bonded-161.55						
Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded						
Status: _Exploration/_XXX_Active/Inactive/_Temporary Cessation/_Bond Forfeiture						
Reclamation (_Phase I/_Phase II/_Final Bond Release/_LiabilityYear)						

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[]	<u> </u>	[]	[]
2.	SIGNS AND MARKERS		П	<u> </u>	i i
3.	TOPSOIL	<u> </u>	Π	Π	Ti .
4.	HYDROLOGIC BALANCE:		_		
a.	DIVERSIONS	[XX]	[]	. []	[]
b.	SEDIMENT PONDS AND IMPOUNDMENTS	XX	[]	$\overline{[XX]}$	[]
c.	OTHER SEDIMENT CONTROL MEASURES	XX	Ξī	[XX]	. []
d.	WATER MONITORING		口		\Box
e.	EFFLUENT LIMITATIONS	$\overline{\Box}$	$\overline{\Box}$	$\overline{\square}$	
5.	EXPLOSIVES	Π		$\overline{\square}$	$\overline{\square}$
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	\Box			፲፲
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	$\overline{[XX]}$	<u>[]</u>	$\overline{[XX]}$	\Box
8.	NONCOAL WASTE	$\overline{[XX]}$	\Box		\Box
9.	PROTECTION OF FISH, WILDLIFE AND			<u>—</u>	
	RELATED ENVIRONMENTAL VALUES		\Box	Ш	Ш
l0.	SLIDES AND OTHER DAMAGE	$\overline{\square}$	$\overline{\square}$		
l1.	CONTEMPORANEOUS RECLAMATION	$\overline{\Box}$	$\overline{\Box}$	\Box	\Box
12.	BACKFILLING AND GRADING	\Box			Ш
13.	REVEGETATION	\Box	\Box	$\overline{\square}$	
l4.	SUBSIDENCE CONTROL		\Box		$\overline{\Box}$
l5.	CESSATION OF OPERATIONS		$\overline{\Box}$		
l6.	ROADS:			- ,	
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[XX]	\Box	\Box	\Box
	DRAINAGE CONTROLS	[XX]	\Box	\Box	\Box
١7.	OTHER TRANSPORTATION FACILITIES	\Box	Ш	\Box	\Box
l8.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	$\overline{[XX]}$	Ш	[XX]	\Box
19.	AVS CHECK (4th Quarter-April, May, June)(date)		$\overline{\Box}$		$ar{\Box}$
20.	AIR QUALITY PERMIT	$\overline{\square}$			ĹÌ
21.	BONDING & INSURANCE	<u> </u>	ĪĪ	[]	[]

INSPECTION REPORT

(Continuation sheet)

Page <u>2</u> of <u>2</u>

PERMIT NUMBER: ACT/007/038

DATE OF INSPECTION: 11/22/99

(Comments are Numbered to Correspond with Topics Listed Above)

4b. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The permittee is in the process of modifying the spillways on four of the site's sediment control impoundments, (001A, 002A, 012A, and 012B).

Mr. Bruce T. S. Ware was on site this day surveying in the primary discharge spillway elevation for pond 001A. The permittee has installed a new 24-inch pipe and riser with oil skimmer to meet the design requirements for the pond and receive "as-built" approval. A 12-inch pipe was originally installed by Nielsen Construction when the pond was built. According to Mr. Ware, the new riser is 0.2 feet lower than what it should be. Mr. Pappas will have this corrected.

Pond 002A is to have the primary spillway lowered 1.5 feet. Mr. Ware was in the process of surveying this in as we left the area.

New sediment level markers will be installed in ponds 011A and 013A.

4c. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

The permittee has completed the riprap channel and steel pipe installation to convert the degasification pump house pad and access road from an ASCA to an area whose drainage reports to sediment pond 001A.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The permittee has moved a portable crusher/screening device onto the School House Canyon refuse pile to initiate the scalping of this pile. This has been permitted through ACT/007/038-99E.

The permittee had not made the repairs to the east bank of the School House Canyon refuse toe pond (013A) as of today's inspection.

18. SUPPORT FACILITIES/ UTILITY INSTALLATIONS

A feeder was observed in the vicinity of the raw coal silo reclaim belt. This unit will be used to add the "scalped" BTU resource material to the washed coal stored at the clean coal storage pile. The addition of this material will enhance the ash fusion temperature requirement for Intermountain Power Agency coal shipments.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Johnny Pappas (Plateau)	Henry Austin (OSM)
Given to: Pam Grubaugh-Littig (DOGM)	Filed to: Price Field Office
Date: December 1, 1999	

Inspector's Signature: #46

Peter Hess